

0006

Surface Inspection Compliance Report

Date of Inspection: November 14, 2000

Case Serial No.: UTU-075888
Operator: Resource Design Solutions, Inc., Joe Dunlop
Project Description: Granite
Legal Description: T. 12 S., R. 07 W., SLM. Section 35
Field Office: Fillmore Field Office
Inspector: J. Mansfield, L. Garahana

Report Narrative (Reference Stipulations by Number or Title):

The operator, Shane Harris, was met on site. Operations at the site were underway when we arrived. On-site were: 1 - 4 wheel-drive pneumatic drill, 1 - large air compressor mounted on trailer, 1 - D-9 bulldozer, 1 - lowboy trailer, 1 - powder magazine, trailer mounted, 1 - camp trailer, 1 - porta-potty, 2 - pick-up trucks, and 1 - storage container 10' x 40'. The operation has expanded beyond their notice to 6.6 acres of disturbance. The operator has been instructed that the site will need to be reclaimed to a level of below five acres of disturbance or a Plan of Operations will have to be filed.

Photo 1 and 2 were taken from the eastern edge of the disturbance facing west. The storage container, powder magazine, camp trailer and port-a-potty are visible. A large overburden pile and a large boulder dragged from the state section are also seen. Photo 3 is facing east and shows the Boulder and drag trail of the boulder from the state section. Photos 4, 5, and 6 are facing west from the middle of the disturbed area show dozer, piles of rock. Photo 7 facing northwest drill rig and pick-up are shown. Photos 8, 9, and 10 facing north from south side of disturbed area high-wall and drill rig shown. Photos 11 and 12 facing north east drill hole patterns in rock are in

Signature of Inspector

Signature of Authorized Officer

0006